From: Miller, Garyq

To: Roberson Tony SWD; Sanchez Carlos

Cc: Leahy Lawrence K SWD

Subject: RE: SAN JACINTO SF SITE (UNCLASSIFIED)

Date: Thursday, February 18, 2016 3:16:00 PM

Attachments: Figure 3 Dec 2015 TEQ Results Aerial.pdf
Figure 2 Dec 2015 TEQ Results.pdf

Figure 2 Dec 2015 TEQ Results.pdf 0557-QIR-006 (Armor Rock Placement) Fig1 pdf

Sed Core Results from San Jacinto Remedial Investigation Report Vol-1 5-2013-2.pdf Surface Sed Results from San Jacinto Remedial Investigation Report Vol-1 5-2013.pdf

## Tony,

As we discussed, here are maps showing the damaged area of the San Jacinto Waste Pits cap as well as the location & results of the shallow (0 - 6") sediment sampling done in December 2015. These samples were collected within the damaged area & from accumulated sediment on top of the underwater portion of the cap.

The damaged area was repaired in December, and I'm also attaching a figure with survey results showing the location of the new armor rock cap material over the damaged area.

Finally, I am attaching several figures showing the sediment sample results located in and around the site; these sample were collected about 5 years ago as a part of the site Remedial Investigation. One of these figures shows the surface sediment (0 - 6") and the other shows the sediment core (10 feet) results.

Please let me know if you have any questions on this.

## Regards,

Gary Miller Remedial Project Manager EPA Region 6 – Superfund Division (6SF-RA) 214-665-8318 miller.garyg@epa.gov

----Original Message-----

From: Roberson, Tony SWD [mailto:Tony.Roberson@usace.army.mil]

Sent: Thursday, February 18, 2016 1:17 PM To: Miller, Garyg; Sanchez, Carlos

Cc: Leahy, Lawrence K SWD

Subject: RE: SAN JACINTO SF SITE (UNCLASSIFIED)

CLASSIFICATION: UNCLASSIFIED

## Gary:

I spoke with Paul (ERDC) earlier and he informed me that EPA may ask ERDC for additional technical support. I was hoping to get a copy of the sample location map and analytical results to determine impacts or risks to the Corps proposed dredging operations. I'd appreciate any info you can share in this regard.

Thanks TONY

TONY R. ROBERSON, REM Chief, Military Integration Division U.S. Army Corps of Engineers, Southwestern Division 1100 Commerce St. Dallas, TX 75242

469.487.7080 BB/Cell: 214.505.0561

Tony.Roberson@usace.army.mil



9752811

----Original Message----

From: Miller, Garyg [mailto:Miller.Garyg@epa.gov] Sent: Thursday, February 18, 2016 12:51 PM

To: Sanchez, Carlos <sanchez.carlos@epa.gov>; Roberson, Tony SWD <Tony.Roberson@usace.army.mil>

Cc: Leahy, Lawrence K SWD <lawrence.k.leahy@usace.army.mil> Subject: [EXTERNAL] RE: SAN JACINTO SF SITE (UNCLASSIFIED)

Tony,

Yes, I am the San Jacinto RPM - please let me know how I can help.

Gary Miller Remedial Project Manager EPA Region 6 ? Superfund Division (6SF-RA) 214-665-8318 miller.garyg@epa.gov

----Original Message-----

From: Sanchez, Carlos

Sent: Thursday, February 18, 2016 12:36 PM

To: Roberson, Tony SWD

Cc: Leahy, Lawrence K SWD; Miller, Garyg

Subject: RE: SAN JACINTO SF SITE (UNCLASSIFIED)

Thanks Tony,

Yes, Gary is the RPM for the San Jacinto Site. I included him on this email..CAS

Carlos A. Sanchez Chief, Superfund AR/TX Section 214-665-8507 Sanchez.carlos@epa.gov

----Original Message-----

 $From: Roberson, Tony\ SWD\ [\underline{mailto:Tony.Roberson@usace.army.mil}]$ 

Sent: Wednesday, February 17, 2016 5:52 PM

To: Sanchez, Carlos

Cc: Leahy, Lawrence K SWD

Subject: SAN JACINTO SF SITE (UNCLASSIFIED)

CLASSIFICATION: UNCLASSIFIED

Carlos:

I just received a copy of the press release for the San Jacinto SF discharge.

Blocked http://yosemite.epa.gov/opa/admpress.nsf/e8f4ff7f7970934e8525735900400c2e/83ddf70854df3fae85257f5c0077e6c5! Open Document the properties of the pr

Some of the Corps and EPA staff were meeting to discuss dredging the Houston Ship Channel and sampling requirements. Is Gary Miller still the RPM? I'd like to get a little more details and information?

Thanks TONY

TONY R. ROBERSON, REM Chief, Military Integration Division U.S. Army Corps of Engineers, Southwestern Division 1100 Commerce St. Dallas, TX 75242

469.487.7080 BB/Cell: 214.505.0561

Tony.Roberson@usace.army.mil

CLASSIFICATION: UNCLASSIFIED CLASSIFICATION: UNCLASSIFIED